

late April '07 Run

John, Megan, Gile @ telescope 4/25/07
AM: SHARC-II problems (batteries rundown?)
testing Larry's old and new code

5° tolerance code ϕ iterations:
moving between 50 and 117

(note: we established that hwp.exe
was not doing any iterations and
has 2° tolerance.)

hwp_0:t_5tol.exe

Error
52.7
52.2
113.8
114.5
52.7
52.1
112.6
53.0
52.2
112.4
53.9
111.9
53.3
52.4
112.2
53.8
52.2

} appears to have 2°
tolerance, not 50

Switch back to hwp.exe



Error

110.0

114.8

53.8

52.8

112.2

53.1

52.8

-bit flip
-bit flip

run

hwg-dit-2tol.exe
(0 iterations, 2² tolerance)

Error

112.1

233

112.7

112.

114.3

115.6

53.00

52.7

bit flip

bit flip

bit flip

problem appears to be with the encoder end of detector

Tried connecting PM4 to spare encoder.
No problems.

Reboot entire system, re-upload hwg-dit-5tol.exe

Run, connect to first encoder.
(Note: encoder V = 13.44)

Error

52.2

52.03

110.8 bit flip

22.32

100.4

54.6

53.0

52.03

(50.892)



-bit 20 bit

52.4
 52.1
 51.9 OK
 110 error
 115.6 error
 115.8 OK
 53.7 error
 52.5 error
 51.0 error
 50.9 error
 50.8 OK

flipping to 220 for many sec.




We had that X2 problem w/ encoder again. It was definitely triggered by stepper but could go off ~~on the middle~~ on its own for no apparent reason. Hard to find any cause and effect, though tusting connectors sometimes helped.

The spare encoder never showed the problem, but we did not test it a lot.

The trick to removing the ~~ser~~ encoder is to access the set screw through the hole in the gear

298°



This is the reference position

With new encoder installed, reference position is

119°

There is roughly 0.2° slack between gears (backlash)

offset between old & new encoder = 179°
~180°

So, instead of starting at 50°, start at 230°, increase in 22.5° increments

Note: new encoder does not have flat edge on shaft, like old encoder

set screw was not tightened on new encoder shaft, however, shaft appears to be well-coupled to gear.

Removed motor shaft - set screw was out (5)

Set screw: $\frac{1}{16}$ " wrench 6-30?

Tried moving hwp with EDAS, IRC. Now
moves to within 0.2° !

April 26 → ~~Wed~~ Thursday (second set-up day)

Aligning SHARC-II (JEU, H.S.)

aperture in ~~far~~ side of Nasayth w.r.t. SHARC-II

<u>File no.</u>	<u>int. time</u> (sec)	<u>Comments</u>
038194	90 sec.	{ for side aperture up. left is 30% brighter than low right
038195	"	

Aligning SHARP JV, GN, HS

<u>File no.</u>	<u>int. time</u>	<u>Comments</u>
38196	60 sec.	exit aperture
38197	"	entrance "

38196 H-array (6.1, 7.3) = (h, v)
V-array (26.8, 6.7) = (h, v)

38197 H-array (5.2, 6.5) = (h, v)
V-array (26.4, 6.0) = (h, v)

links:

<http://cv5588.gsfc.nasa.gov/webstart/share/share.html>

entrance aperture

038198

H-array (~~5.2~~, ~~6.5~~) =

V-array (26.4, 6.0) =
after dinner entrance is good
~~near aperture~~ exit aperture

by eye : at least $\frac{1}{2}$ pix

$\frac{3}{4}$ pixel high in both

half pixel left in both

by eye after shims removed

V-array: good up/down
left by about $\frac{1}{2}$ pixel

H-array: low by $\frac{1}{3}$ pixel
left by $\frac{1}{3}$ pixel

removing shims move exit ap. down 1



~~exit up~~
entrance aperture

V-array

down $1\frac{3}{4}$
~~left~~ right $\frac{1}{3}$ pixel

H-array

down $2\frac{1}{2}$
 left $\frac{1}{3}$ pixel

removing mirror shims moves entrance
 aperture down ~~2~~ pixels

{ Now the entrance ap down 2
 exit up good
 entrance is low rel. to exit
 before the entrance good
 the exit high by $\frac{3}{4}$
 entrance low rel to exit

removing shims makes entrance low rel.
to exit 42 mils under mirror

after puzzle
Entrance aperture

V: $\left\{ \begin{array}{l} \frac{3}{4} \text{ pix high} \\ \frac{1}{3} \text{ pix right} \end{array} \right.$

H: $\left\{ \begin{array}{l} \frac{1}{2} - \frac{3}{4} \text{ pix high} \\ \text{good left/right} \end{array} \right.$

Exit aperture

V: $\left\{ \begin{array}{l} 1 \text{ pixel high} \\ \frac{1}{3} \text{ pixel left} \end{array} \right.$

H: $\left\{ \begin{array}{l} \frac{3}{4} \text{ high} \\ \frac{1}{3} - \frac{1}{2} \text{ left} \end{array} \right.$

Arg for 'N

V: $\left\{ \begin{array}{l} \frac{7}{8} \text{ high} \\ \text{centered} \end{array} \right.$

H: $\left\{ \begin{array}{l} \frac{3}{4} \text{ high} \\ \frac{1}{6} - \frac{1}{4} \text{ left} \end{array} \right.$

Removed box 3 to repair hwp.

The set screw had gotten loose again and we saw bad waves (often 8° skew): Even w/ 2 iterations only occasionally got to desired position. John noticed cases of overshooting. The culprit was a loose set screw. So we disassembled and re-tightened set screw. This time I really torqued it hard. I may have stripped the ~~head~~ socket of the set screw. ~~The~~

Just to be clear: this is the motor shaft coupling to gear,

In the process of debugging, we verified that the spare index works, but it needs to have

its default parameters set properly. This should be done before it is needed. According to manual ~~it~~ it is OK to power up w/o motor attached. Just can't disconnect or connect motor to indexes while index is powered.

Also ~~nicked~~ nicked hwp w/ coating once or twice while ~~repairing~~ tightening the set screw.

We observed for 1/2 hour (polarimetry of B335) and hwp was good to $\pm 0.1^\circ$ on every move
also I checked reference mark to verify encoder didn't slip


Fri night

hwp worked well, but there were 4 bad moves out of ~ 200 .

See observing log excel sheet. The rest of the moves were good to $\pm 0.1^\circ$ or 0.2° . We heated to room temp. Note we saw the bit-flip problem. \leftarrow

Sat night

In order to guard against encoder problem (slipping due to lack of set screw tightening) I made a mark that you can see when SHAK is installed.



even w/ spare encoder!

⊙ grid test

Apr 30 2007 UT
(Sunday; night 4)

wires 2.5 deg ccw from vertical

signal at night in IRC

(assumed to be V):

HWP

70 -80

80 -40

90 -20

100 -23

110 -50

120 -83

~~signal at left~~

signal at left (assumed H)

90 -200, -180

100 -205

110 -181

70 -150

80 -186

110 -184

90 -210

→ J of hwp points towards
 SNARC-II for positive direction
 of encoder

blue mark still at 96°

starting up. → got one error
 on 3rd move "encoder not
 responding". This was on one
 practice move.

this was either cause plate too hot... or
 some ~~weird~~ weird start-up issue?

A few scattered errors noted in
 excel spreadsheet

May 1 UT last night

Did quick $\pm 2^\circ$ check of gear-mark
 at 96° . IT was good.

5/1 7:45am

Grid tests

grids are aligned 2.19' CW from vertical
(viewed w/ SHARP)

Taking ~~hot~~ ~~load~~ files with level at
1st hoop angle w/ hot load in
place

SHARP single file \rightarrow 1 file
standard file \rightarrow 1 file

June '07 RUN

Lamy, Gile, Hua-bai, Hinko present
at setup

June 8th. ~~Re~~ Installing 450mm hwp.
See p. 178 of instrument log #1
removed continuous cork spacer*

NOTE: BRING DOUBLE-SIDED TAPE FOR
CONVERSION TO 350mm

NOTE: I don't think cork is doing
anything. hwp is lodged (stuck)
into metal retainer.

NOTE: we want working ethernet ahead of time

Today Lamy & Gile got the 450mm installed,
got EPTS + hwp working inside, then
installed box 3 and got it all working
outside

H-Bai & Hinko got initial data on SHARC-II
alignment. entrance ap. looks pretty centered

* store in 450mm HWP case

NOTE: buy a parastrip and store it
at CSO

H-bai & Hiroko also installed box 2

June 9th

SNARC-II alignment done as He-3
running out all-gain-low

exit
aperture

-100 -100
-70 -70

entrance
apertures

-45 | -45 repeat -30 -30
-30 | -30 -20 -20

They are parallel but off by
something less than $\frac{1}{2}$ pixel.

Decided not to adjust.

cherry picker test

2007/06/10 UTC (17)

Giles, Hnabai, Hiroko

① cold center

~~2x~~

Bolo Array -250 -300 ish

Bolometer median black ~~-285~~

-.279 -.240 -.259

② cold out

Bolo ~~array~~
medium

min -.17 max 0

mean 0.011 → level

Bolo medium

-0.8×10^{-4} max $8E-3$

9×10^{-4} → level

-2×10^{-4}

③ cold center

Bolo medium

-.29

$2.8E-3$

-.10

④ cold out

-.28

$1.5E-3$

-.140 → level

④ cold out

Bolometer Frame Median (voice)

2.2×10^{-3}

cold

⑩ out -.011 → level $6.2E-04$

⑤ cold center

-.290

⑪ cold right -.307

⑥ cold out

$-7.9E-4$

⑫ out $-4E-03$

⑦ cold top

-.248

⑬ left 2.147

⑧ cold out

$8.65E-3$

⑭ out $-4E-03$ →

⑨ cold bottom

-.247

15 cold top middle -0.316

16 out $-2.58E-3$

17 bottom middle $= 0.318$

18 out $-1.3E-3$

19 right ~~left~~ middle $= 0.319$

20 out $-7.9E-03$

21 left middle -0.316

22 out $-8.5E-3$

23 cold center -0.299

24 out -0.012

248

316

147

316

290
(299)

319

307

318

247

you have to
roll your mouse
over the trace



Note: we were looking at
BOLOMETTER FRAME MEDIAN
(VOLTS) which is plotted in
the bolometer medians window

NOTE WE ARE ASSUMING V IS ON ~~RIGHT~~ LEFT
 OF DISPLAY

entrance ap.

after adjustment
 of H minor

V good L/R
 1 pix high

good L/R
 1 pix high

H $\frac{1}{2}$ pix left
 1 pix high

good L/R
 $\frac{3}{4}$ pix high

exit aperture

V left $\frac{1}{3}$
 $\frac{7}{8}$ high

$\frac{3}{8}$ left
 1 high

H left $\frac{1}{3}$
 1 high

$\frac{1}{8}$ left
 $\frac{3}{4}$ high

avg V left $\frac{1}{6}$
 1 pix hi

avg V $\frac{3}{16}$ left
 1 high

avg H left $\frac{1}{2}$
 1 pix hi

avg H $\frac{1}{16}$ left
 $\frac{3}{4}$ high

after 2nd adj (of V_{minor}
this time)

good L/R
 $\frac{5}{8} - \boxed{\frac{3}{4}}$ high
~~error error~~

good L/R
 $\frac{7}{8}$ high

$\frac{3}{8}$ left

$\frac{5}{8}$ high

good L/R

$\frac{3}{4}$ high

avg V $\frac{3}{16}$ left

$\frac{5}{16}$ high

avg H good L/R

$\frac{13}{16}$ high

~~worst case~~

worst case $\frac{1}{16}$


V-H is $\frac{3}{16}$ fix

worst case

parallelism error

is $\frac{3}{8}$ pix

DSOS.



we checked sharp w/ level

error is 0.1° and 0.15° for the
two axes.

↑
parallel to
light propagation

searching for v-null

	(V)	(H)
50	0	-158
72.5	-65	-100
95	-158	0
117.5	-100	-65

assumes V is
on left of display

~~117.5~~ 117.5 ~~117.5~~ 117.5 ~~117.5~~ 117.5